

Quality of Water of Polluted River stretches in Punjab for the month of February, 2022

Beas (along Mukerian) : Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	08/02/2022	S43	ZO Lab, Jal	8.1	8.8	1.1	240	280	79	0.072	0.35	0.50	B	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO ₃ -N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	08/02/2022	S43	ZO Lab, Jal	14	20	48	140	112	14	12	97	28	7	81	BDL	1.1	1.4	1.8	0.17	0.15	7.9	2.5

Note. 1. BDL means Below Method Detection Limit
2. DBU means Designated Best Use (Class-A, B, C,D & E)
3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)
4. U/s means Upstream, D/s means Downstream