Quality of Water of Polluted River stretches in Punjab for the month of February, 2023

Beas (along Mukerian): Priority IV

S	N. Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
	1 Kali Bein into Beas	2913	17/02/23	55	ZO Lab, Jal	7.8	5.4	2.1	265	1700	680	0.04	0.74	0.68	C	S

S	5.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l		TSS mg/l		FDS mg/l	Cl mg/l	SO4 Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3- N mg/l	TKN mg/l	PO4as P mg/l	F mg/l	Na mg/l	K mg/l
	1	Kali Bein into Beas	2913	17/02/23	55	ZO Lab, Jal	12	10	14	156	118	16	13	100	25	9.2	94	BDL	1.1	1.5	1.8	0.18	0.22	17	5.1

Note. 1. BDL means Below Method Detection Limit

^{2.} DBU means Designated Best Use (Class-A, B, C,D & E)

^{3.} Water Quality Index (S means Satisfactory, U means Unsatisfactory)

^{4.} U/s means Upstream, D/s means Downstream