## Quality of Water of Polluted River stretches in Punjab for the month of January, 2021

## Kali Bein (Sultanpur Lodhi to Confluence to Beas): Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T.Coli MPN/ 100ml	FColi MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	21/1/2021	SW 25	ZO Lab, Jalandhar	7.3	4	2.9	284	1500	390	0.006	0.60	0.57	С	S

S.N	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/ l	Cl mg/ l	SO <sub>4</sub> Mg/ l	TH mg/l	Ca mg/ l	Mg mg/ l	T.Alk n mg/l	p.Alkn mg/l	Amn- N mg/l	NO3-N mg/l	TKN mg/l	PO <sub>4</sub> as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	21/1/20 21	SW 25	ZO Lab, Jalandhar	18	6.7	BDL	176	142	14	16	90	26	6	92	BDL	0.6	0.8	1.6	0.11	0.16	13	4.4