## Quality of Water of Polluted River stretches in Punjab for the month of June, 2020

## Beas (along Mukerian): Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	04/06/2020	SW 257	ZO Lab Jal.	7.9	7.0	1.3	266	470	110	0.041	0.43	0.25	В	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO <sub>4</sub> Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3-N mg/l	TKN mg/l	PO <sub>4</sub> as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	04/06/2020	SW 257	ZO Lab Jal.	13	32	13	176	138	16	12	124	35	9	134	BDL	0.9	0.8	1.6	0.09	0.17	11	2.3

Note. 1. BDL means Below Method Detection Limit

- 2. DBU means Designated Best Use (Class-A,B,C,D & E)
- 3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)
- 4. U/s means Upstream , D/s means Downstream