Quality of Water of Polluted River stretches in Punjab for the month of June, 2021

Kali Bein (Sultanpur Lodhi to Confluence to Beas): Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T.Coli MPN/ 100ml	FColi MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	21.6.2021	247	ZO Lab, Jal	7.2	7.1	2.6	326	2100	940	0.018	1.07	0.49	С	s

S.N	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/	Cl mg/ l	SO ₄ Mg/ l	TH mg/l	Ca mg/ l	Mg mg/ l	T.Alk n mg/l	p.Alkn mg/l	Amn- N mg/l	NO3-N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	21.6.2021	247	ZO Lab, Jal	18	4	BDL	210	155	30	18	131	39	8	113	BDL	1.8	2.1	1.9	0.19	0.19	28	13