Quality of Water of Polluted River stretches in Punjab for the month of May, 2021

Beas (along Mukerian): Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	12/05/21	182	ZO Lab, Jal	7.9	7.7	1.6	225	390	78	0.041	0.31	*	В	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l		Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3- N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	12/05/21	182	ZO Lab, Jal	18	16	BDL	142	115	13	15	84	30	2	92	BDL	0.9	2.0	1.8	0.08	0.17	6.4	2.4

Note. 1. BDL means Below Method Detection Limit

- 2. DBU means Designated Best Use (Class-A, B, C,D & E)
- 3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)
- 4. U/s means Upstream, D/s means Downstream