

## Quality of Water of Polluted River stretches in Punjab for the month of June, 2023

### Beas (along Mukerian) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond $\mu$ s/Cm	T. Coli MPN/100ml	F. Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	07/06/23	S215	ZO Lab, Jal	7.5	4.6	3	306	3400	1300	0.022	0.81	0.41	C	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO4 Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3-N mg/l	TKN mg/l	PO4as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	07/06/23	S215	ZO Lab, Jal	18	20	28	182	149	16	12	114	29	10	110	BDL	1.1	1.9	1.8	0.22	0.22	20	3.5

Note. 1. BDL means Below Method Detection Limit

2. DBU means Designated Best Use (Class-A, B, C,D & E)

3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)

4. U/s means Upstream, D/s means Downstream