Quality of Water of Polluted River stretches in Punjab for the month of October, 2022

Beas (along Mukerian): Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	12/10/22	501	ZO Lab, Jal	7.8	7.1	1	229	480	260	0.04	0.25	0.27	В	S

S	S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l		SO ₄ Mg/l		Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3- N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
	1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	12/10/22	501	ZO Lab, Jal	8	42	38	143	122	12	9	84	21	7.8	108	ND	1.2	1.0	1.6	0.10	0.18	5.3	2.8

Note. 1. BDL means Below Method Detection Limit

- 2. DBU means Designated Best Use (Class-A, B, C,D & E)
- 3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)
- 4. U/s means Upstream, D/s means Downstream

Analysis results of Surface water monitoring under NWMP for the month of October, 2022 (Metal/Pesticides)

River Beas

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	T.Cr mg/l	Ni mg/l	Fe mg/l	Zn mg/l	Cu mg/l	Pb mg/l	Cd mg/l	As mg/l	Hg mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	12/10/22	501	ZO Lab Jal.	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL

Note. 1. BDL means Below Method Detection Limit

^{2.} Pesticides i.e. Alpha HCH, Beta HCH, Gama HCH, Anilophos, Chloropyrifos, 4,4' DDT, OP-DDT, Endosulphan-1, Endosulphan-2, Dieldrin, Aldrin, Methyl Parathion & Malathion were BDL.