

Quality of Water of Polluted River stretches in Punjab for the month of August, 2021

Kali Bein (Sultanpur Lodhi to Confluence to Beas) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond μ s/Cm	T.Coli MPN/100ml	F.Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	23/8/21	SW 333	ZO Lab, Jal	7.1	4.0	2.3	328	1400	790	0.001	1.07	0.75	C	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/l	Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alk n mg/l	p.Alkn mg/l	Amn-N mg/l	NO ₃ -N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	23/8/21	SW 333	ZO Lab, Jal	15	44	12	172	136	26	18	111	33	7	72	BDL	2.5	1.9	3.1	0.15	0.16	26	13