

Quality of Water of Polluted River stretches in Punjab for the month of December, 2021

Beas (along Mukerian) : Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond μ s/Cm	T. Coli MPN/100ml	F. Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	10/12/21	472	ZO Lab, Jal	8.0	8.0	1.2	279	460	92	0.055	0.31	0.40	B	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO ₃ -N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	10/12/21	472	ZO Lab, Jal	16	21	10	160	135	16	13	104	32	6	81	BDL	1.1	1.2	1.8	0.16	0.15	7.2	3.2

Note. 1. BDL means Below Method Detection Limit

2. DBU means Designated Best Use (Class-A, B, C,D & E)

3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)

4. U/s means Upstream, D/s means Downstream