

## Quality of Water of Polluted River stretches in Punjab for the month of July, 2021

### Beas (along Mukerian) : Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond $\mu$ s/Cm	T. Coli MPN/100ml	F. Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	08/07/2021	268	ZO Lab, Jal	8.1	7.0	1.1	222	430	94	0.039	0.36	0.35	B	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO <sub>4</sub> Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO <sub>3</sub> -N mg/l	TKN mg/l	PO <sub>4</sub> as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	08/07/2021	268	ZO Lab, Jal	15	130	68	140	117	15	13	107	29	8	94	BDL	0.6	1.2	1.6	0.06	0.17	8.6	2.9

Note. 1. BDL means Below Method Detection Limit

2. DBU means Designated Best Use (Class-A, B, C,D & E)

3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)

4. U/s means Upstream, D/s means Downstream