

Quality of Water of Polluted River stretches in Punjab for the month of March, 2021

Kali Bein (Sultanpur Lodhi to Confluence to Beas) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond μ s/Cm	T.Coli MPN/100ml	F.Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	15/3/21	SW 106	ZO Lab, Jal	7.9	4.9	2.6	288	1700	780	0.036	0.83	0.70	C	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/l	Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alk n mg/l	p.Alkn mg/l	Amn-N mg/l	NO ₃ -N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	15/3/21	SW 106	ZO Lab, Jal	15	2	BDL	179	132	14	12	89	26	6	88	BDL	0.8	0.7	1.8	0.07	0.18	18	2.6