

Quality of Water of Polluted River stretches in Punjab for the month of May, 2020

Kali Bein (Sultanpur Lodhi to Confluence to Beas) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond μ s/Cm	T.Coli MPN/100ml	F.Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	20/5/2020	SW 219	Z.O. Lab Jalandhar	7.6	5.3	3.2	324	4700	1100	0.018	0.85	0.24	D	U

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/l	Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alk n mg/l	p.Alkn mg/l	Amn-N mg/l	NO ₃ -N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	20/5/2020	SW 219	Z.O. Lab Jalandhar	24	62	16	204	170	22	12	113	31	9	134	BDL	0.7	0.7	1.3	0.15	0.16	21	4.5