

## Quality of Water of Polluted River stretches in Punjab for the month of November, 2020

### Kali Bein (Sultanpur Lodhi to Confluence to Beas) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond $\mu$ s/Cm	T.Coli MPN/100ml	F.Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Water quality as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	11/11/20	SW 615	ZO Lab, Jal	7.4	4.1	2.3	322	1400	390	0.012	0.80	0.55	C	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	CO D mg/l	Turb NTU	TSS mg/l	TDS mg/l	FD S mg/l	Cl mg/l	SO <sub>4</sub> Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alk n mg/l	p.Alkn mg/l	Amn-N mg/l	NO <sub>3</sub> -N mg/l	TKN mg/l	PO <sub>4</sub> as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	11/11/20	SW 615	ZO Lab, Jal	15	44	15	206	169	14	18	98	25	8	100	BDL	0.8	0.9	1.6	0.10	0.18	18	4.0