

Quality of Water of Polluted River stretches in Punjab for the month of December, 2022

Beas (along Mukerian) : Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond μ s/Cm	T. Coli MPN/100ml	F. Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	12/12/22	588	ZO Lab, Jal	7.4	4.2	1.5	262	2800	1400	0.02	0.74	0.48	C	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO4 Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3-N mg/l	TKN mg/l	PO4as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	12/12/22	588	ZO Lab, Jal	9	12	7	168	135	16	12	88	23	7.3	108	ND	1.4	1.2	2.0	0.16	0.22	16	2.3

Note. 1. BDL means Below Method Detection Limit

2. DBU means Designated Best Use (Class-A, B, C,D & E)

3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)

4. U/s means Upstream, D/s means Downstream