Quality of Water of Polluted River stretches in Punjab for the month of July, 2022

Beas (along Mukerian): Priority IV

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pН	DO mg/l	BOD mg/l	Cond µs/Cm	T. Coli MPN/ 100ml	F. Coli MPN/ 100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	Kali Bein into Beas	2913	25/07/2022	SW 396	ZO Lab, Jal	7.3	5.2	2.9	235	1700	260	0.053	1.42	0.65	С	s

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU		TDS mg/l		Cl mg/l	SO ₄ Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO3- N mg/l	TKN mg/l	PO ₄ as P mg/l	F mg/l	Na mg/l	K mg/l
1	Kali Bein into Beas	2913	25/07/2022	SW 396	ZO Lab, Jal	20	40	110	149	122	22	14	56	14.4	4.9	92	BDL	1.4	1.4	2.4	0.13	0.12	24.52	4.87

Note. 1. BDL means Below Method Detection Limit

^{2.} DBU means Designated Best Use (Class-A, B, C,D & E)

^{3.} Water Quality Index (S means Satisfactory, U means Unsatisfactory)

^{4.} U/s means Upstream, D/s means Downstream