

## Quality of Water of Polluted River stretches in Punjab for the month of December, 2022

### Beas (along Mukerian) : Priority V

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	pH	DO mg/l	BOD mg/l	Cond $\mu$ s/Cm	T. Coli MPN/100ml	F. Coli MPN/100ml	Free Amm. mg/l	SAR	B mg/l	Quality of water as per DBU	Water Quality Index
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	19/12/22	607	ZO Lab, Jal	8.2	8.7	1.2	285	350	170	0.09	0.39	0.29	B	S

S.N.	Point of Sample Collection	Code	Date of receipt in lab	Lab Sample No.	Sample Collected & Analyzed by	COD mg/l	Turb NTU	TSS mg/l	TDS mg/l	FDS mg/l	Cl mg/l	SO <sub>4</sub> Mg/l	TH mg/l	Ca mg/l	Mg mg/l	T.Alkn mg/l	P.Alkn mg/l	AmnN mg/l	NO <sub>3</sub> -N mg/l	TKN mg/l	PO <sub>4</sub> as P mg/l	F mg/l	Na mg/l	K mg/l
1	River Beas 1 Km D/S effluent discharge point at Mukerian	1294	19/12/22	607	ZO Lab, Jal	8	21	18	174	142	10	9	118	30	11	132	ND	1.1	1.0	1.8	0.15	0.17	9.8	2.8

Note. 1. BDL means Below Method Detection Limit

2. DBU means Designated Best Use (Class-A, B, C,D & E)

3. Water Quality Index (S means Satisfactory, U means Unsatisfactory)

4. U/s means Upstream, D/s means Downstream